

INFORMATION UPDATE

Problems with the Mitsubishi Triton 6 Speed Jumping Out of 3rd Gear?

ATC has developed the 3K-V6M5A Repair Kit specifically to help deal with this problem.

This kit comes with:

- ▶ New 3rd Gear
- ▶ New 3rd/4th Synchro Sleeve
- ▶ New 3rd/4th Shift Fork
- ▶ New 3rd/4th Shift Lever
- ▶ New 3rd/4th Shift Lever Pin
- ▶ New 3rd/4th & 5th/6th Detent Springs

Kit is available for both 2WD and 4WD



ALSO AVAILABLE



We now also have the K-MIT4600 gearbox rebuild kit to suit the 04/15 on Mitsubishi Triton 6 Sp, as well as synchro rings to suit not only this but a wide range of other gearboxes as well....